

EXHIBIT D**ASSIGNED LAND AND REAL PROPERTY IMPROVEMENTS
(CONCESSION FACILITIES)****Land Assigned**

Land is assigned in accordance with the boundaries shown on the map on the following page.

Real Property Improvements Assigned

The following real property improvements are assigned to the concessioner for use in conducting its operations under this Contract:

| FMSS Asset Code | FMSS Asset Description | FMSS Asset Type | Quantity in Square Feet | Date Built or Installed | Historic (Y or N) | Insurance Replacement Value |
|-----------------|---|-----------------|-------------------------|-------------------------|-------------------|-----------------------------|
| 42609 | Glacier Bay Lodge GBL16 | 4100 | 15,118 | 1966 | Yes | \$4,444,503 |
| 42644 | Lodge Service Building GBL17 | 4100 | 826 | 1972 | Yes | \$54,822 |
| 42717 | Lodge Guest Cabins 1-4 - GBQ16A | 4300 | 1,663 | 1966 | Yes | \$300,571 |
| 42724 | Lodge Admin / Staff Building GBL71 | 4100 | 2,290 | 1990 | No | \$620,612 |
| 70962 | Heating Fuel System GBL16, GBL17, Guest Cabins 9-56 | 5700 | 1 (#) | 1999 | No | \$89,089 |
| 70964 | Heating Fuel System Guest Cabins GBQ01-08 | 5700 | 1 (#) | 1986 | No | \$27,931 |
| 70966 | Heating Fuel System | 5700 | 1 (#) | 1996 | No | \$27,271 |
| 73317 | Lodge Guest Cabins 5-6 / U1 - GBQ16B | 4300 | 1242 | 1966 | Yes | \$74,420 |
| 73341 | Lodge Guest Cabins 9-12 & 14-15 - GBQ16C | 4300 | 5,175 | 1972 | Yes | \$856,048 |
| 73350 | Lodge Guest Cabins 7-8 - GBQ16D | 4300 | 844 | 1966 | Yes | \$166,057 |
| 73361 | Lodge Guest Cabins 16-21 - GBQ16E | 4300 | 2,175 | 1972 | Yes | \$378,994 |
| 73364 | Lodge Guest Cabins 22-25 - GBQ16F | 4300 | 1,664 | 1966 | Yes | \$300,701 |
| 73367 | Lodge Guest Cabins 26-27 - GBQ16G | 4300 | 835 | 1966 | Yes | \$164,470 |
| 73370 | Lodge Guest Cabins 28-31 - GBQ16H | 4300 | 1,447 | 1972 | Yes | \$265,249 |
| 73372 | Lodge Guest Cabins 32-34 / U2 - GBQ16I | 4300 | 1,452 | 1972 | Yes | \$266,108 |
| 73375 | Lodge Guest Cabins 35-38 - GBQ16J | 4300 | 1,459 | 1972 | Yes | \$267,289 |
| 73380 | Lodge Guest Cabins 39-42 - GBQ16K | 4300 | 1,452 | 1972 | Yes | \$266,108 |
| 73382 | Lodge Guest Cabins 43-46 - GBQ16L | 4300 | 1,459 | 1972 | Yes | \$267,289 |
| 73383 | Lodge Guest Cabins 47-50 GBQ16M | 4300 | 1,459 | 1972 | Yes | \$267,289 |
| 73386 | Lodge Guest Cabins 51-52 / U3 - GBQ16N | 4300 | 1,241 | 1966 | Yes | \$213,664 |
| 73387 | Lodge Guest Cabins 53-54 - GBQ16O | 4300 | 640 | 1966 | Yes | 129,958 |
| 73389 | Lodge Guest Cabins 55-56 - GBQ16P | 4300 | 640 | 1966 | Yes | \$129,958 |

| FMSS Asset Code | FMSS Asset Description | FMSS Asset Type | Quantity in Square Feet | Date Built or Installed | Historic (Y or N) | Insurance Replacement Value |
|-----------------|---|-----------------|-------------------------|-------------------------|-------------------|-----------------------------|
| 73395 | Lodge Baggage Storage Building GBL16R | 4100 | 320 | 1985 | Yes | \$26,192 |
| 73529 | Lodge Housing Parking Area (Service Road F) GLBA-0906 | 1300 | 19,499 | 1976 | No | |
| 84205 | Lodge Staff Dormitory Building GBQ56 | 4300 | 1,728 | 1978 | No | \$432,484 |
| 84216 | Lodge Staff Dormitory Building GBQ57 | 4300 | 1,728 | 1976 | No | \$432,484 |
| 84218 | Lodge Staff Dormitory Building GBQ58 | 4300 | 1,920 | 1976 | No | \$465,043 |
| 92848 | Propane Fuel System | 5700 | 1 (#) | 1990 | No | \$29,877 |
| 226564 | Staff Kitchen Dry Storage Annex GBL71A | 4100 | 96 | 1993 | No | \$6,573 |
| 230312 | Glacier Bay Lodge Boardwalk East | 2100 | 1,284 (L.F.) | 1965 | Y | \$190,254 |
| 230315 | Glacier Bay Lodge Boardwalk West | 2100 | 284 (L.F.) | 1965 | Y | \$45,011 |
| 94379 | Lodge Storage/Maintenance Shed GBL65 | 4100 | 120 | 1990 | No | \$5,285 |

** Please note: The lack of value for an asset in the column for Insurance Replacement Value does not relieve the Concessioner of its obligation to insure the asset according to the terms of this Contract.*

Approved, effective _____, 20____

By: _____


Regional Director, Alaska Region

Land Assigned

Notes:

NPS is responsible for all road maintenance
 NPS is responsible for maintenance of GLBA Lodge parking lot
 Concessioner is responsible for maintenance of housing area parking lot
 NPS is responsible for maintenance of 230312 and 230315 (Boardwalks)
 For #42609, see Exhibit H, Maintenance Plan, for maintenance responsibilities

----- Designates Land Assignment boundary



BASIC DATA: BOUNDARY MAP 132/96,004 10/78